

	Diplomat Dental s.r.o., Vrbovská cesta 17, 921 01 Piešťany, Slovak Republic		
	Change description: New Conectors for foot controllers	Change is valid for: Model Pro - all	Technical information No: 001
			Change is valid from: 12.2022

New connector for the foot controllers UNO and NOK

We hereby inform you about the change of the connector and socket of the foot controllers.

The connector and socked change was prompted by issues with the possibility of the connector being incorrectly connected.

Original connector DELTRON CONNECTOR 610-0800 (ME374522.042) will be replaced with connector **SV 80 LUMBERG – (ME374522.044)**.

Original socket SOCKET DELTRON 651-0800 (ME374522.043) will be replaced with socket **KFV 80 LUMBERG – (ME345571.015)**.

The replaced connectors will be a part of all foot control cables for Model PRO and all the front covers of the chair base, on which the socket is attached.

The change also applies to the design of the UNO and NOK wireless foot controllers sold after December 2022

The new socket requires a larger size of the hole into which it is attached.

The change concerns to all orders and service interventions for dental unit and spare parts sold after December 2022.