DIPLOMAT DENTAL SOLUTIONS	Diplomat Dental s.r.o., Vrbovská cesta 17, 921 01 Piešťany, Slovak Republic		
	Change description: New version of FW	Change is valid for: Model One 100	Technical information No: 002
			Change is valid from: 09.03.2023

# **New FW package version**

We hereby inform you about the release of a new version of the firmware package for electronics of the Model One 100 dental units.

New FW version is available form 09.03.2023

# Firmware package v 1.0.5

#### Changes:

### 1. In the new FW package 1.0.5, individual FWs will have the following numerical designation.

Item No.	Module name	Firmware number
ME374000.476	MODUL TB_EKO1	1.0.0.1
ME374000.475	MODUL SB_EKO1	1.0.0.1
ME374000.500	MODUL CHES_GREAT	1.0.1.A
ME374000.453	MODUL CHES_GREAT	1.0.1.A
ME374000.454	MODUL FC_PREM_TKC2	1.0.0.C
ME374000.455	MODUL FC_PREM_TUC2	1.0.0.C
ME374000.450	MODUL AB_PREM2	1.0.0.7

### 2. The new firmware includes the following:

- 1. Modification of semiautomatic hygiene for Model One control panel with 7-segment display.
- 2. Adjustment for workspace and max. Densim micromotor temperature
- 3. Adjustment for functions of stopping the chair with a joystick when chair moves to the getting on position.
- 4. The possibility of more precise setting of the torque of the DXPRO micromotor.